



General Growth Properties – Columbia Mall

Project Scope:

Removed existing loose gravel surfacing, installed one layer of 1" polyisocyanurate insulation and Sika Sanafil RhinoBond roofing system utilizing 60-mil Sikaplan membrane.

Sika Sarnafil Rhinobond roofing system selected as an alternative to a conventional mechanically attached system for increased project productivity and to eliminate fasteners penetrating the field sheet.

The RhinoBond system utilizes PVC coated securement plates that are induction welded to the underside of the field sheet.

```
[stm_project_details style="style_2" title="PROJECT DETAILS" css=".vc_custom_1428651906989{margin-bottom: 41px !important;}"]  
[stm_project_details_item label="Operating Unit:" value="Roofing Services and Solutions – Columbia"]  
[stm_project_details_item label="Client" value="General Growth Properties"]  
[stm_project_details_item label="Industry Type: " value="Retail"]  
[stm_project_details_item label="Project Type:" value="Re-Roof"]  
[stm_project_details_item label="Location:" value="Columbia, MO"]  
[stm_project_details_item label="Square Footage:" value="480,000 square feet"]  
[stm_project_details_item label="Systems Installed:" value="Rhinobond"]  
[/stm_project_details]  
[stm_contacts_widget title="CONTACT INFO" address="1835 Old Highway 40 East Columbia, Missouri 65202" phone="573-886-7988" email="jlauberth@tectaaamerica.com"]
```